

Structural Stability Certificate- II

1. Certified that the construction of building has been done as per approved plan on and bearing Khasra Nos.279,28,288 to 293,295, 407 to 412, 453,454 & 453/1. situated at Up Mohal Bag Teh. And Distt. Una Himachal Pradesh. The construction satisfied the safety requirements and the information given there in is correct to the best of my / our knowledge and understanding.
2. It is further certified that the structural design, including safety, from natural hazards including earthquake resistance, as per the guidelines for hazard safety, issued been prepared by qualified structural Engineer at least B.E. (Civil) or equivalent, duly registered with the institute of Engineers (India)

Signature of the officer in Charge / Authority / Owner / Applicant:.....

Date

Name in block Letters: DAYANAND PUBLIC SCHOOL UNA

Address:- WARD NO.4 UP MOHAL BAG TEHSIL AND DISTT. UNA (H.P.)

Signature of the Structural Engineer: -

Name in Block Letter:-

Registration No. Date:- 03/09/2025

Address:- *Er. Narinder Paul Saini*
B.E. Civil, M. Tectr. (Structure); G.E., M.E., FIV
CE No. 96132-1, TCP Regn. No. RS0002/2016
Structure Engineer
Opp. Sanik Rest House, 1st Floor, Una (H.P.)
(M)- 94180-58990, 98165-58990, 94182-54020

Signature of the Architect / Authorized Signatory:-.....

Name in Block Letter:-

Registration No. Date:- 03/09/2025

Address:- *Er. Narinder Paul Saini*
B.E. Civil, M. Tech. (Structure), C.E., M.E., FIV
CE No. 96132-1, TCP Regn. No. A (a) - 46
Architect, Engineer, Valuer, Development Consultant
Opp. Sanik Rest House, 1st Floor, Una (H.P.)
(M)- 94180-58990, 98165-58990, 94182-54020